
DIE / MOULD RACK







Die and Mould racks are very convenient to use die / mould storage devices with a built in lifting and lowering chain hoist. The drawers are sturdy and can be pulled out and pushed back with the load.

In order to remove a die or mould from the rack simply put out the drawer on which the mould is placed. Pull the monorail trolley and the chain hoist above the mould. Attach the hook of the hoist to the mould. Lift the mould with the chain hoist about 2 inches above the drawer. Push back the drawer into the rack and lower the mould to the ground or to a pallet lying in front of the rack. The mould can now be moved to the machine with a pallet truck. Simple isn't it. For loading the mould/die simply follow the reverse

For loading the mould/die simply follow the reverse procedure.

Specifications:

MR-1000	
1000kg	
3100 x 840 x 2550mm	
900 x 600mm	
9 nos	
380mm	
1000kg	
850kg	
700kg	
2000kg	

LOKPAL INDUSTRIES

A-6, Sector-3, Noida-201301, U.P., India | Tel.: +91-120-3065372 / 75 Website: www.lokpal.com | E-mail: info@lokpal.com